

Billet size (100x100x100)mm  
 cutter diameter = 6mm

→ CNC Milling:

N1 G21 G94

N2 G28 X0 Y0 Z0

N3 G90

N4 M06 T01

N5 M03 S1200

N6 G00 X10 Y10 Z5

N7 G01 Z-1 F3

N8 G01 X90 Y10

N9 G01 X90 Y90

N10 G01 X10 Y90

N11 G01 X10 Y10



N12 G00 Z5

N13 G28 X0 Y0 Z0

N14 M05

N15 ~~M30~~

~~Jan~~  
~~October~~



2)

N1 G21 G94

N2 G28 X0 Y0 Z0

N3 G90

N4 M06 T01

N5 M03 S1200

N6 G00 X20 Y10 Z5

N7 G01 Z-1 F3

N8 G01 X80 Y10

N9 G01 X90 Y20

N10 G01 X90 Y80

N11 G03 X80 Y90 R10

N12 G01 X20 Y90

N13 G01 X10 Y80

N14 G01 X10 Y20

N15 G02 X20 Y10 R10


N16 G00 Z5

N17 G28 X0 Y0 Z0

N18 M05

N19 M30

~~As per~~



1) write a part program to perform mirroring operation on the component along x-axis.

N1 G21 G94

N2 G28 X0 Y0 Z0

N3 G90

N4 M06 T01

N5 M03 S1200

N6 G00 X0 Y0 Z5

N7 M98 P001 3333

N8 M70

N9 M98 P001 3333

N10 M80

N11 G28 X0 Y0 Z0

N12 M05 M30

N13 O 3333

N14 G00 X0 Y20 Z5

N15 G01 Z-1 F5

N16 G01 X50 Y20

N17 G01 X60 Y60

N18 G03 X-60 Y60 R100



N19 G01 X-50 Y20

N20 G01 X0 Y20

N21 G00 Z5

N22 X0 Y0

N23 M99



2) write a part program to perform mirroring operation on the component along x-axis. cutter dia = 6mm

G21 G94

G28 X0 Y0 Z0

G90

M06 T01

M03 S1200

G00 X0 Y0 Z5

M98 P001 3333

M71

M98 P001 3333

M81

G28 X0 Y0 Z0

M05 M30

D 3333

G00 X20 Y0 Z5

G01 Z-1 F5

G01 X20 Y50

G01 X60 Y60

G02 X60 Y-60 R100

G01 X20 Y-50


G01 X20 Y0

G00 Z5

X0 Y0

M99





3) write a part program to perform mirroring operation on the contour as shown (both x-axis and y-axis)

G21 G94

G28 X0 Y0 Z0

G90

M06 T0101

M03 S1200

G00 X0 Y0 Z1

M98 P001 4444

M70

M98 P001 4444

M80

M71

M98 P001 4444

M81

M70

M71

M98 P001 4444

M80

M81

G28 X0 Y0 Z1

M05

M30

O 4444

G00 X10 Y10 Z5

G01 Z-1 F5

X10 Y40

Expt. No. ....

Date

X40 Y10

X10 Y10

G00 Z5

X0 Y0

M99

~~05/12/20~~

→ Drilling operation (G73 cycle)

Syntax - G73 X Y Z P Q R F K

→ Hole depth

→ Position of hole

→ Drill code

P - Dwell time (milli seconds)



Q - Peck increment (mm)

R - Reference point

F - Feed (mm/min)

K - no. of holes

~~Done~~



1. write a part program to perform drilling operation on the component as shown.

N1 G21 G94

N2 G28 X0 Y0 Z0

N3 M06 T0101

N4 M03 S800

N5 G91 X10 Y50 Z-20 P500 Q1 R1 K1 F5

N6 X10 Y0 R2

N7 G80

N8 G28 X0 Y0 Z0

N9 G91 X50 Y10 Z-20 P500 Q1 R1 K1 F5

N10 X0 Y10 R2

N11 G80

N12 G28 X0 Y0 Z0

N13 M05

N14 M30

~~Done~~  
~~order~~